

Randall W. Hardy, Superintendent Charles Royer, Mayor

April 29, 1985



Mr. Phillip Ishop, General Manager Highland Supply, Inc. P.O. Box 3422 Humble, Texas 77388

Dear Mr. Ishop:

As per your request on 24 April (Wednesday) to my staff, please find enclosed a copy of analytical results for PCB testing performed on Bunker C oil at our Lake Union Steam Plant. We are sending this data in lieu of the sample oil itself, which you had previously requested (10 April letter).

Feel free to contact Mr. Terry Kakida of my staff (Ph. 206-625-3799) with any further questions.

Thank you for your interest in this matter.

Sincerely,

Timothy C. Croll, Acting Director Environmental Affairs Division

TK:jf

Encl.

cc: Terry Kakida EAD File

"An Equal Employment Opportunity – Affirmative Action Employer"

City of Seattle – City Light Department, City Light Building, 1015 Third Avenue, Seattle, Washington 98104 (206) 625-3000



4900 9TH AVENUE N.W., . SEATTLE, WASHINGTON 95107-3697 . 206/783-4700

ANALYSIS REPORT

CLIENT: Seattle City Light

DATE RECEIVED: 4/20/84

REPORT TO: Mr. Al Cuplin

DATE REPORTED: 4/24/84

3613 - 4th Avenue So. Bldg. B, Room 11 Seattle, WA 98134

CONTRACT NO. 138780-09

ANALYSIS OF OIL FOR PCB'S

Sample No.	Client Identification			Aroclor Type		Concentration µg/g	
75813	4204-1	LUSP	MAIN	TAUK	TOP	1242	75.5
75814	4204-2	LUSP	••	••	SUCTION	1242	68.5

Garry Duschl

GD:kw

SEA315426